

FID	OBJECTID	created_at	updated_at	version	status	latitude	longitude	type	type_other	material	material_o	condition	sediment	water_qual	maintenanc	photos		
0	1	2016-05-18	2016-05-18	1	inspected	40.2331652	-105.291165	Conveyance,Box		Other	60x28 concrete	Acceptable	Moderate	None		Hand Tools	c444bea3-9c81-428a-a773-48d6d4579fa2	
1	2	2016-05-18	2016-05-18	1	inspected	40.2331909	-105.2911585	Conveyance,Box		Other	60x28 concrete	Acceptable	High	None		Hand Tools	92590ad3-6d32-4a94-817e-be2c9767dfbe	
2	3	2016-05-18	2016-05-18	1	inspected	40.2482842	-105.2898495	Conveyance,Box		Other	75x75 con	New	Low	None		Hand Tools	ba47c948-7c75-4c4f-9e3f-3fd1c1794c0f	
3	4	2016-05-18	2016-05-18	1	inspected	40.2480579	-105.2898487	Conveyance,Box		Other	75x75 con	New	Low	None		Hand Tools	868dcf9b-44fb-492a-ad9b-2ceb88b7da43	
4	5	2016-05-18	2016-05-18	1	inspected	40.2423174	-105.2911063	Conveyance,Pipe		Metal		Deficient	Moderate	None		Hand Tools	f902b669-c895-4aa0-809e-31d8d46d387f1,5fa37a1b-a3e0-49cd-b0bf-6012a5d5684d	
5	6	2016-05-18	2016-05-18	1	inspected	40.2413708	-105.2912574	Conveyance,Pipe		Other	18 in. CMP	Acceptable	Moderate	None		Hand Tools	3d17cd01-8a34-4e6b-a606-99aa9f4d725,5c794881-d671-400f-a61d-6b111110565c	
6	7	2016-05-18	2016-05-18	1	inspected	40.2393558	-105.2909709	Conveyance,Pipe		Other	36in cmp	Acceptable	Low	None		Power Tools	3049475f-7e4f-4c27-b80a-0456b79ed3d4d,e125b429-498e-4e42-8682-d5068e653344	
7	8	2016-05-18	2016-05-18	1	inspected	40.2311476	-105.2889191	Conveyance,Pipe		Other	18in cmp	Deficient	High	None		Hand Tools	7df68910-66df-424c-b399-091e6d2c0c0f	
8	9	2016-05-18	2016-05-18	1	inspected	40.2312295	-105.2886781	Conveyance,Pipe		Other	24in cmp	Good	Low	None		Hand Tools	1e4a34e3-96d9-4cfe-8959-9daaacc1c38c8	
9	10	2016-05-18	2016-05-18	1	inspected	40.2301823	-105.2885815	Conveyance,Pipe		Other	36in cmp	Acceptable	Low	None		Hand Tools	7ea18e3f-ce41-48e0-a5d2-7c9afe57aa51	
10	11	2016-05-18	2016-05-18	1	inspected	40.2301503	-105.2883225	Conveyance,Pipe		Other	36in cmp	Good	Low	None		Hand Tools	23cd477f-cd66-47ad-bc0f-321bc55287915	
11	12	2016-05-18	2016-05-18	1	inspected	40.2290742	-105.2883208	Conveyance,Pipe		Other	12in cmp	Deficient	High	None		Power Tools	f72a5592-1890-42af-a005-d91b154ae899	
12	13	2016-05-18	2016-05-18	1	inspected	40.2291115	-105.2881939	Conveyance,Pipe		Other	12in cmp	Deficient	High	None		Power Tools	b8882161-1aad-4cd1-875b-20ccb08639d9	
13	14	2016-05-18	2016-05-18	1	inspected	40.2278534	-105.2956397	Conveyance,Pipe		Other	18in plastic	Good	Low	None		Hand Tools	25fbc4d6-5d8c-4b42-b93f-b09114df832	
14	15	2016-05-18	2016-05-18	1	inspected	40.2280352	-105.2956501	Conveyance,Pipe		Other	18in plastic	Good	Moderate	None		Hand Tools	4726490f-74ea-44af-8219-d2e272bbc0b	
15	16	2016-05-18	2016-05-18	1	inspected	40.2389236	-105.2878973	Conveyance,Pipe		Other	24in con	New	Low	None		Hand Tools	f31d7c3f-2bf1-4b00-97af-8eacaf34b3ac	
16	17	2016-05-18	2016-05-18	1	inspected	40.2388568	-105.2878418	Conveyance,Pipe		Other	24 con	New	Low	None		Hand Tools	329fe083-4c36-4631-b926-0ab23f954ae6	
17	18	2016-05-18	2016-05-18	1	inspected	40.2433555	-105.2873077	Conveyance,Pipe		Other	24in con	New	Low	None		Hand Tools	63c47341-3093-455b-bb64-200873bbc9eb	
18	19	2016-05-18	2016-05-18	1	inspected	40.2433988	-105.2875433	Conveyance,Pipe		Other	24in con	New	Low	None		Hand Tools	6441290d-e321-4154-9ab1-40c6eb211e	
19	20	2016-05-18	2016-05-18	1	inspected	40.2447981	-105.2866839	Conveyance,Pipe		Other	36in con	New	Low	None		Hand Tools	3fb3464-2352-41a5-b2d3-439380752e8	
20	21	2016-05-18	2016-05-18	1	inspected	40.2448842	-105.2870547	Conveyance,Pipe		Other	36in con	New	Low	None		Hand Tools	d851443f-4672-4146-b514-62b98d34f658	
21	22	2016-05-18	2016-05-18	1	inspected	40.2474342	-105.2870062	Conveyance,Pipe		Other	36in con	New	Low	None		Hand Tools	53b76ab5-e895-4a7a-9909-ab116a1e5e6e	
22	23	2016-05-18	2016-05-18	1	inspected	40.2473807	-105.2871685	Conveyance,Pipe		Other	36in con	New	Low	None		Hand Tools	1030c520-23a1-4bae-9cca-45238c720126	
23	24	2016-05-18	2016-05-18	1	inspected	40.2480354	-105.2893543	Conveyance,Pipe		Other	36in con	New	Low	None		Hand Tools	64594d81-df4f-4a30-a09a-7bc41cdcc971d	
24	25	2016-05-18	2016-05-18	1	inspected	40.2482343	-105.2893009	Conveyance,Pipe		Other	36in con	New	Low	None		Hand Tools	7b3ebae8-9317-40dc-bd38-9d9ec842b718	
25	26	2016-05-18	2016-05-18	1	inspected	40.2175219	-105.2591607	Conveyance,Pipe		Other	24in cmp	Good	Low	None		Hand Tools	6faeaa95-3162-4e8f-b6e3-a317e52a3260	
26	27	2016-05-18	2016-05-18	1	inspected	40.2314862	-105.2794515	Conveyance,Pipe		Other	48in con	Good	Moderate	None		Hand Tools	2465deeb-ac85-4e9e-9f5b-4b2e9326814	
27	28	2016-05-18	2016-05-18	1	inspected	40.2295659	-105.2762046	Inlet,Grate		Concrete		Good	Moderate	None		Hand Tools	445afdd6-a1d8-4c3a-bc0a-2bd5b7570746	
28	29	2016-05-18	2016-05-18	1	inspected	40.2482546	-105.2909442	Inlet,Grate		Concrete		New	Low	None		Hand Tools	6048ed07-9971-49b1-acf4-2e35b20b9b13	
29	30	2016-05-18	2016-05-18	1	inspected	40.231203	-105.2786585	Inlet,Grate		Concrete		Good	Low	None		Hand Tools	68bee461-bf84-4a73-aad1-bedd41c35f4	
30	31	2016-05-18	2016-05-18	1	inspected	40.2299535	-105.2765276	Inlet,Vault		Other	16ft	Good	Low	None		Hand Tools	832ca3b5-c880-47d3-bed0-0dab3f3cd05f	
31	32	2016-05-18	2016-05-18	1	inspected	40.2308538	-105.2805609	Inlet,Vault		Other	5ft concrete	Good	Low	None		Hand Tools	87abb321-7282-4e9d-9f44-721c7264de34	
32	33	2016-05-18	2016-05-18	1	inspected	40.231314	-105.2802544	Inlet,Vault		Other	5ft concrete	Good	Low	None		Hand Tools	cb969067-8a24-4d17-aedc-c46ff857370	
33	34	2016-05-18	2016-05-18	1	inspected	40.2318222	-105.2795581	Inlet,Vault		Other	5ft concrete	Good	Low	None		Hand Tools	f2644f0f-06cf-4fc8-b76d-19195a7d92d2	
34	35	2016-05-18	2016-05-18	1	inspected	40.2319115	-105.2795971	Inlet,Vault		Other	10ft concrete	Good	Low	None		Hand Tools	0b4353fa-01a4-4454-b20b-317fd006437a	
35	36	2016-05-18	2016-05-18	1	inspected	40.2327013	-105.2797183	Inlet,Vault		Other	10ft con	Good	Low	None		Hand Tools	c42fd690-81d2-4371-ab8c-6915f19d3b6e	
36	37	2016-05-18	2016-05-18	1	inspected	40.232806	-105.2799045	Inlet,Vault		Other	5ft con	Good	Low	None		Hand Tools	5c4c8893-a213-4c1f-ba9b-6af4f99a0bdd	
37	38	2016-05-18	2016-05-18	1	inspected	40.2480894	-105.290929	Outlet,Pipe		Other	24in con	New	Low	None		Hand Tools	798acb15-19f5-4668-a0c3-fcdadd8a6e05	
38	39	2016-05-18	2016-05-18	1	inspected	40.214927	-105.2722927	Conveyance,Box		Other	72x24 con	New	Low	None		Hand Tools	87b56e54-b8c8-4f5d-b2c3-8a7b844792a5	
39	40	2016-05-18	2016-05-18	1	inspected	40.2149311	-105.2722092	Conveyance,Box		Other	72x24in	New	Low	None		Hand Tools	877c78eb-1a11-48e7-81bc-726f2182a45f	
40	41	2016-05-18	2016-05-18	1	inspected	40.2194159	-105.2566276	Conveyance,Box		Other	8ftx13ft	Good	Low	None		Hand Tools	6b1a075c-7b10-4aa6-a6b5-1cb65304276e	
41	42	2016-05-18	2016-05-18	1	inspected	40.2197487	-105.2566101	Conveyance,Box		Other	8ftx13ft	Good	Low	None		Hand Tools	c80ad50b-d603-4a49-b91b-d65d35a6c2b1,3f31c2d1c-27c-4fa9-bfa8-e7bc16c3882f	
42	43	2016-05-18	2016-05-18	1	inspected	40.2187822	-105.2588601	Conveyance,Box		Other	4x12ft	Good	Low	None		Hand Tools	7717b8cf-dd9b-488e-8653-74252b06f8e	
43	44	2016-05-18	2016-05-18	1	inspected	40.218614	-105.2588147	Conveyance,Box		Other	4x12ft	Good	Low	None		Hand Tools	d24c735-14c2-45f1-bd29-015e7ca2a74	
44	45	2016-05-18	2016-05-18	1	inspected	40.2168896	-105.2743606	Conveyance,Other	Bridge									
45	46	2016-05-18	2016-05-18	1	inspected	40.2226678	-105.2715795	Conveyance,Other	Bridge									
46	47	2016-05-18	2016-05-18	1	inspected	40.2167204	-105.2630615	Conveyance,Other	MH	Concrete		Good						
47	48	2016-05-18	2016-05-18	1	inspected	40.2152228	-105.2600741	Conveyance,Other	MH									
48	49	2016-05-18	2016-05-18	1	inspected	40.2153835	-105.259708	Conveyance,Other	MH									
49	50	2016-05-18	2016-05-18	1	inspected	40.2153626	-105.2595767	Conveyance,Other	Detention	Rock		Good	Low	None		Hand Tools	583d0e4c-6e5e-45af-b155-068501b8ef84	
50	51	2016-05-18	2016-05-18	1	inspected	40.2141902	-105.2600874	Conveyance,Other	MH									
51	52	2016-05-18	2016-05-18	1	inspected	40.2142278	-105.2600818	Conveyance,Other	MH									
52	53	2016-05-18	2016-05-18	1	inspected	40.2140845	-105.2601591	Conveyance,Other	MH									
53	54	2016-05-18	2016-05-18	1	inspected	40.2141146	-105.2599145	Conveyance,Other	MH									
54	55	2016-05-18	2016-05-18	1	inspected	40.2143574	-105.2599775	Conveyance,Other	MH									
55	56	2016-05-18	2016-05-18	1	inspected	40.2136764	-105.2608023	Conveyance,Other	MH									
56	57	2016-05-18	2016-05-18	1	inspected	40.2147836	-105.2597888	Conveyance,Other	MH									
57	58	2016-05-18	2016-05-18	1	inspected	40.2150597	-105.2599233	Conveyance,Other	MH									
58	59	2016-05-18	2016-05-18	1	inspected	40.2159243	-105.2607987	Conveyance,Other	MH									
59	60	2016-05-18	2016-05-18	1	inspected	40.2177675	-105.2601132	Conveyance,Other	Bridge									
60	61	2016-05-18	2016-05-18	1	inspected	40.2133509	-105.2746192	Conveyance,Pipe		Other	18in cmp	Acceptable	Moderate	None		Hand Tools	cd4b36c6-81c7-4b79-aa6b-7868bdaa319,2510f4ee-da50-4f49-a4da-1b9fd2af0b01	
61	62</																	



166	167	2016-05-19	2016-05-19	1	inspected	40.2235603	-105.266796	Inlet,Grate	Metal		Good	Low	44f26140-d374-4e25-bae3-57a43de74d3
167	168	2016-05-19	2016-05-19	1	inspected	40.2234747	-105.2673747	Inlet,Grate	Metal		Good	Low	c413ec67-fe65-490e-b58c-c435b209be7
168	169	2016-05-19	2016-05-19	1	inspected	40.2236389	-105.267229	Inlet,Grate	Metal		Good		68a298e9-1cdc-4546-8814-dac712dd81f3
169	170	2016-05-19	2016-05-19	1	inspected	40.2236668	-105.2698235	Inlet,Grate	Metal		Good		af06a04-11f0-4a9a-82fe-a407635f30c
170	171	2016-05-19	2016-05-19	1	inspected	40.2236544	-105.270023	Inlet,Grate	Metal		Good	Low	427cbca0-01dc-4e92-b713-128b3ef1212
171	172	2016-05-19	2016-05-19	1	inspected	40.2236633	-105.2702192	Inlet,Grate	Metal		Good	Low	350ab18b-19c8-4bbe-9e35-7c2256250af6
172	173	2016-05-19	2016-05-19	1	inspected	40.223486	-105.2715266	Inlet,Grate	Metal		Good		53605db3-d89c-42d1-b601-cl45b11166e
173	174	2016-05-19	2016-05-19	1	inspected	40.2237538	-105.2715395	Inlet,Grate	Metal		Good	Moderate	092e386d-6818-4dde-860e-fbca702e4634
174	175	2016-05-19	2016-05-19	1	inspected	40.2234773	-105.2711476	Inlet,Grate	Metal		Good	Low	c68f3b58-cdfa-4ec5-a178-7ca0523533d1
175	176	2016-05-19	2016-05-19	1	inspected	40.2230521	-105.2715545	Inlet,Grate	Metal		Deficient		8dcd07c-da7a-460c-b271-0a02c8e71157
176	177	2016-05-19	2016-05-19	1	inspected	40.2232022	-105.2715433	Inlet,Grate	Metal		Acceptable	High	49599547-2859-4fdd-b179-546e22e200e2
177	178	2016-05-19	2016-05-19	1	inspected	40.2231853	-105.2709451	Inlet,Grate	Metal		Acceptable		469ea321-3176-4811-9c55-71a25c0d0150
178	179	2016-05-19	2016-05-19	1	inspected	40.2232322	-105.2710827	Inlet,Grate	Metal		Good		f39a137-eabb-40a5-992e-c8f15d133001
179	180	2016-05-19	2016-05-19	1	inspected	40.2231071	-105.2707346	Inlet,Grate	Metal		Good		62f0118-3b05-40b5-a460-88302f133008
180	181	2016-05-19	2016-05-19	1	inspected	40.2291889	-105.2663996	Inlet,Grate	Metal		Good		852c700-8062-433b-9a27-b50a3c4b4ab8
181	182	2016-05-19	2016-05-19	1	inspected	40.2292462	-105.2662106	Inlet,Grate	Metal		Acceptable	Moderate	738736c-41a1-469f-aacd-97c9578b9129
182	183	2016-05-19	2016-05-19	1	inspected	40.2277616	-105.265969	Inlet,Grate	Metal		Good		c3bb5e58-5694-43dc-bb83-e8a05d3f5a29
183	184	2016-05-19	2016-05-19	1	inspected	40.2276147	-105.2677105	Inlet,Grate	Metal		Good		9f0a0b9e-2c5d-4639-afdd-1f18287d6d63
184	185	2016-05-19	2016-05-19	1	inspected	40.2265129	-105.2680967	Inlet,Grate	Metal		Good	High	96699797-92fd-4144-b8fe-c922746197f0
185	186	2016-05-19	2016-05-19	1	inspected	40.2267243	-105.2697667	Inlet,Grate	Metal		Good	Low	0abd1d6-2293-475b-84b8-f24a9f0d49d
186	187	2016-05-19	2016-05-19	1	inspected	40.2267102	-105.2704128	Inlet,Grate	Metal		Good		a79fbb80-c339-48fb-8ebb-42b3243914e
187	188	2016-05-19	2016-05-19	1	inspected	40.2266446	-105.2704336	Inlet,Grate	Metal		Good		55e853d-5f52-4d01-9cfc-eaee90182d9f
188	189	2016-05-19	2016-05-19	1	inspected	40.2257047	-105.2715044	Inlet,Grate	Metal		Good	Low	63a9b71f-87ea-4057-9496-23903705c695
189	190	2016-05-19	2016-05-19	1	inspected	40.2255084	-105.2697223	Inlet,Grate	Metal		Good		9c1b385-1848-4f9b-b990-61478d0c22dd
190	191	2016-05-19	2016-05-19	1	inspected	40.2255033	-105.2699113	Inlet,Grate	Metal		Good		ec197755-9022-423c-87b0-aed4d64e65c9
191	192	2016-05-19	2016-05-19	1	inspected	40.2253489	-105.2699542	Inlet,Grate	Metal		Good		39f8340d-9036-474a-8835-b057b5c53098
192	193	2016-05-19	2016-05-19	1	inspected	40.2257915	-105.2722905	Inlet,Grate	Metal		Good		6feea83f-222d-402c-b28f-53c54ce0cbea
193	194	2016-05-19	2016-05-23	2	inspected	40.2251553	-105.2711853	Inlet,Grate	Metal		Good		a5f733ba-3dc4-4bea-a13f-1f7e8bc36c5f
194	195	2016-05-19	2016-05-19	1	inspected	40.2239101	-105.2700164	Inlet,Grate	Metal		Good		f40ea86f-911f-4dd2-bde0-a061123b8774
195	196	2016-05-19	2016-05-19	1	inspected	40.224113	-105.2690117	Inlet,Grate	Metal		Good		4f8603e1-1766-47b2-964e-338277acbd0
196	197	2016-05-19	2016-05-19	1	inspected	40.2251341	-105.2675733	Inlet,Grate	Metal		Good	High	8f982ec5-f77e-41b1-8028-15dde6f1e17
197	198	2016-05-19	2016-05-19	1	inspected	40.2248056	-105.2675356	Inlet,Grate	Metal		Good	High	81b2a2f1-17d7-48b7-b809-757bbaf1790f
198	199	2016-05-19	2016-05-19	1	inspected	40.2266333	-105.2654244	Inlet,Grate	Metal		Good	High	fa4b8923-28e6-48e1-9615-04429a1c9c5b
199	200	2016-05-19	2016-05-19	1	inspected	40.2265972	-105.2650378	Inlet,Grate	Metal		Good	Moderate	cf631813-d364-43dd-956c-4e8428e12597
200	201	2016-05-19	2016-05-19	1	inspected	40.2231894	-105.2653051	Inlet,Grate	Metal		Good	Moderate	ac37b32a-b3bc-4e38-bfe7-0478754a4f9
201	202	2016-05-19	2016-05-19	1	inspected	40.2230623	-105.2655738	Inlet,Grate	Metal		Good	Moderate	4ad0c92-9f5d-44d4-9969-8f8843cc2f50
202	203	2016-05-19	2016-05-19	1	inspected	40.2220591	-105.2644204	Inlet,Grate	Metal		Good	Low	15d0bc67-74f0-4eb6-aa4a-4ee8f5c7130c
203	204	2016-05-19	2016-05-19	1	inspected	40.2192627	-105.2658289	Inlet,Pipe	Other	36x48in rcp	Deficient	High	e327639a-3d88-4bfc-ab2d-864bc470c38
204	205	2016-05-19	2016-05-19	1	inspected	40.2212209	-105.2653441	Inlet,Pipe	Other	18in cmp	Acceptable	Moderate	6c732389-e6d4-4379-9b06-1aba5935abf5
205	206	2016-05-19	2016-05-19	1	inspected	40.2225865	-105.267394	Inlet,Pipe	Other	18in pvc	Good		59920e4-b8b1-480a-884e-aac208d11a654
206	207	2016-05-19	2016-05-19	1	inspected	40.2228773	-105.2658799	Inlet,Pipe	Other	36in rcp	New		f57a41c0-2d8e-4bb1-8d07-38924f1c7183
207	208	2016-05-19	2016-05-19	1	inspected	40.2237033	-105.2673317	Inlet,Pipe	Other	24in cmp	Good	Low	145c29e0-4630-4e5b-8f39-1018d820c8b
208	209	2016-05-19	2016-05-19	1	inspected	40.2266995	-105.2648906	Inlet,Pipe	Other	30in cmp	Good	High	7e5f5420-7348-4ca4-94ec-530de38a787b
209	210	2016-05-19	2016-05-19	1	inspected	40.2235518	-105.265363	Inlet,Pipe	Other	12in cmp	Acceptable	Moderate	7e57540d-f05-4ab3-bea7-5f33a270e71b
210	211	2016-05-19	2016-05-19	1	inspected	40.2214936	-105.2644357	Inlet,Vault	Other	3ft	Good		55422a0c-0370-4d76-9c2c1-4446965202f
211	212	2016-05-19	2016-05-19	1	inspected	40.2213908	-105.2645293	Inlet,Vault	Other	5ft	Good		e47e096a-df15-42f0-b119-ce13c86b56a8
212	213	2016-05-19	2016-05-19	1	inspected	40.2218403	-105.2644691	Inlet,Vault	Other	5ft	New		f1a42726-6f57-4421-b256-df145468a9e
213	214	2016-05-19	2016-05-19	1	inspected	40.2219432	-105.264636	Inlet,Vault	Other	5ft	New		00f79751-e81c-4e99-afdc-dacd5e6b32a
214	215	2016-05-19	2016-05-19	1	inspected	40.222721	-105.2656092	Inlet,Vault	Other	10ft	New		546e7a0e-dae1-4b1e-9c8a-0f6fd2b6313e
215	216	2016-05-19	2016-05-19	1	inspected	40.2215018	-105.267299	Inlet,Vault	Other	10ft	New		9b0c7daa-8f25-4b2b-a054-6587aaf5fecb
216	217	2016-05-19	2016-05-19	1	inspected	40.221501	-105.2674874	Inlet,Vault	Other	10ft	New		7edde489-b39e-4542-a5d9-e5d04f951e9
217	218	2016-05-19	2016-05-19	1	inspected	40.2231169	-105.2676306	Inlet,Vault	Metal	Other	5ft	Low	cfb0a365-316a-4c26-bfd9-b8ddcb179c91
218	219	2016-05-19	2016-05-19	1	inspected	40.2239874	-105.2690311	Inlet,Vault	Other	5ft	Good		62158c67-5d15-4ecd-be0c-63c8a170ac85
219	220	2016-05-19	2016-05-19	1	inspected	40.2302468	-105.2713803	Inlet,Vault	Other	5ft	Good		487a24ce-9f68-41b7-b05e-3e1a53156a14
220	221	2016-05-19	2016-05-19	1	inspected	40.2309321	-105.2706749	Inlet,Vault	Other	5ft	Good		7bd5c11c-28e4-4dce-929f-53d1d6404dc1
221	222	2016-05-19	2016-05-19	1	inspected	40.2309193	-105.2707259	Inlet,Vault	Other	10ft	Good		981194dd-0e19-4e20-8d67-0ccb32862a01
222	223	2016-05-19	2016-05-19	1	inspected	40.2310306	-105.2707445	Inlet,Vault	Other	10ft	Good		64cd6420-5547-4b49-a958-183841e50395
223	224	2016-05-19	2016-05-19	1	inspected	40.232492	-105.2695643	Inlet,Vault	Other	15ft	Good	Low	e3fbbde1-3940-4d7f-9c90-e932a17635a5
224	225	2016-05-19	2016-05-19	1	inspected	40.2322223	-105.2696765	Inlet,Vault	Other	10ft	Good		b4b92867-2d44-49c0-9e8f-c0c565c4b0fc
225	226	2016-05-19	2016-05-19	1	inspected	40.2315109	-105.2687897	Inlet,Vault	Other	4ft	Good		62b044a1-81bc-4c18-a87c-faa76ec560fa
226	227	2016-05-19	2016-05-19	1	inspected	40.231636	-105.2687384	Inlet,Vault	Other	5ft	Good		5a0f7659-894a-40dd-b79c-34800b301c1f
227	228	2016-05-19	2016-05-19	1	inspected	40.2277685	-105.2703885	Inlet,Vault	Rock		Acceptable	Low	0464235d-57f3-414d-a1ca-5adf52121d47
228	229	2016-05-19	2016-05-19	1	inspected	40.2255263	-105.2716835	Inlet,Vault	Other	5ft	Good	Low	2c2fb2f2-d20c-452b-aed8-a0469a756ca
229	230	2016-05-19	2016-05-19	1	inspected	40.2255467	-105.2719377	Inlet,Vault	Other	15ft	Good	Low	0a49db95-0869-4948-bdeb-5bf230b735a0
230	231	2016-05-19	2016-05-19	1	inspected	40.2264102	-105.2728955	Inlet,Vault	Other	15ft	Good		a729763e-d6db-4ae9-9947-570f92375a66
231	232	2016-05-19	2016-05-19	1	inspected	40.2277096	-105.2742588	Inlet,Vault	Other	15ft	Good		87ab8f40-f477-46ae-8bad-dc4d36eaf8dc
232	233	2016-05-19	2016-05-19	1	inspected	40.2254876	-105.2722475	Inlet,Vault	Metal		Good		9f8fa320-3130-4260-a3b9-110a7fd3d8e1
233	234	2016-05-19	2016-05-19	1	inspected	40.2242172	-105.2715182	Inlet,Vault	Other	5ft	Good		92bac5e5-aa31-45f2-9b90-703fa9c87b89
234	235	2016-05-19	2016-05-19	1	inspected	40.2244481	-105.2715132	Inlet,Vault	Other	5ft	Good		e46d4bb6-0856-4e97-ae8f-196c3550e4f9
235	236	2016-05-19	2016-05-19	1	inspected	40.2240348	-105.2701709	Inlet,Vault	Other	5ft	Good		743a7cfe-b1e7-46e8-b5d0-34436a176133
236	237	2016-05-19	2016-05-19	1	inspected	40.2246009	-105.2685068	Inlet,Vault	Other	5ft	Good		f9a0e937-a371-477b-81b7-923a49f8889
237	238	2016-05-19	2016-05-19	1	inspected	40.2246997	-105.2684221	Inlet,Vault	Other	5ft	Good		00836d68-9e69-4ae0-9eaf-3bc8fcb92c37
238	239	2016-05-19	2016-05-19	1	inspected	40.2247566	-105.2685698	Inlet,Vault	Other	5ft	Good	Moderate	7c6329f2-29fd-430e-b6bb-48d964c04e8
239	240	2016-05-19	2016-05-19	1	inspected	40.2246376	-105.2681707	Inlet,Vault	Other	5ft	Good		8e6d45dc-1630-4b5f-b306-98abd352a01
240	241	2016-05-19	2016-05-19	1	inspected	40.2248379	-105.2699926	Inlet,Vault	Other	5ft	Good		784c5aaa-d972-4414-8d61-477c80e01e5a
241													



333	334	2016-05-23	2016-05-23	1	inspected	40.227213	-105.2865411	Conveyance,Pipe	Other	18in	Acceptable	Moderate	a2b91c55-24ab-4032-be6c-569309214bb1
334	335	2016-05-23	2016-05-23	1	inspected	40.2273141	-105.2867482	Conveyance,Pipe	Other	18in cmp	Deficient	High	d70f570d-9389-4cc2-ac23-b04c6dcabb67
335	336	2016-05-23	2016-05-23	1	inspected	40.2270893	-105.2864085	Conveyance,Pipe	Other	18in	Deficient	High	763cd465-380a-4fa5-a915-7d033f5788de
336	337	2016-05-23	2016-05-23	1	inspected	40.2271093	-105.2864084	Conveyance,Pipe	Other	18in	Acceptable	Moderate	258d2f3e-b201-4f3a-a133-351c60265d60
337	338	2016-05-23	2016-05-23	1	inspected	40.2267674	-105.2858156	Conveyance,Pipe	Other	18in	Good	Moderate	db4aad26-c30a-4a74-8bcb-1bc6f031f240
338	339	2016-05-23	2016-05-23	1	inspected	40.2268139	-105.2859508	Conveyance,Pipe	Other	18in	Acceptable	High	2fcbf9f-8fe0-47f3-bc0d-6c41cce9617
339	340	2016-05-23	2016-05-23	1	inspected	40.2267232	-105.2855515	Conveyance,Pipe	Other	18in	Deficient	High	0ab9a406-679f-4cb7-bb5a-3ba3ec8385eb
340	341	2016-05-23	2016-05-23	1	inspected	40.2268325	-105.2856151	Conveyance,Pipe	Other	18in	Deficient	High	f3e21461-2d4a-425f-86ce-54d6925ad1b8
341	342	2016-05-23	2016-05-23	1	inspected	40.2314807	-105.2820093	Conveyance,Pipe	Other	24in cmp	Good	Moderate	bcc2e3f0-94bb-470c-a0fa-93020d58b95f
342	343	2016-05-23	2016-05-23	1	inspected	40.230872	-105.2823282	Conveyance,Pipe	Other	24in cmp	Acceptable	Moderate	7137f803-99f1-44d3-a93e-3ad612b211d2
343	344	2016-05-23	2016-05-23	1	inspected	40.2423415	-105.2879863	Conveyance,Pipe	Other	24in	New	Low	7b78bb38-1bf3-4e04-ac45-d6440aabdc1d2
344	345	2016-05-23	2016-05-23	1	inspected	40.2422793	-105.2877377	Conveyance,Pipe	Other	24in rcp	New	Low	8ccdebd7-7ab1144a4-911f-fa63516ccddc
345	346	2016-05-23	2016-05-23	1	inspected	40.2415369	-105.2880813	Conveyance,Pipe	Other	24in rcp	New	Low	5415edc7-fab1144a4-911f-fa63516ccddc
346	347	2016-05-23	2016-05-23	1	inspected	40.2415837	-105.2878304	Conveyance,Pipe	Other	24in	New	Low	e04d8848-d087-77ef-8bb6-9e5f3ce56a80
347	348	2016-05-23	2016-05-23	1	inspected	40.2398579	-105.2880598	Conveyance,Pipe	Other	24in rcp	New	Low	71fac15-54d0-4a5b-b559-1b839126a2a2
348	349	2016-05-23	2016-05-23	1	inspected	40.2400477	-105.2878606	Conveyance,Pipe	Other	24in rcp	New	Low	ae2b626c-7fce-4bb-9810-44238cfadcb
349	350	2016-05-23	2016-05-23	1	inspected	40.2393199	-105.2880301	Conveyance,Pipe	Other	3x5 rcp	Acceptable	High	a1cdc7ef-d0e9-4604-b6e0-b0da92f56ea5
350	351	2016-05-23	2016-05-23	1	inspected	40.2393416	-105.2880234	Conveyance,Pipe	Other	3x5 rcp	Acceptable	Moderate	9391f595-0c7c-499f-bdc7-1d582811170
351	352	2016-05-23	2016-05-23	1	inspected	40.2392715	-105.2878186	Conveyance,Pipe	Other	24in rcp	New	Low	017f3586-6ea4-4c8a-ac1d-a97d697656c5
352	353	2016-05-23	2016-05-23	1	inspected	40.2391028	-105.2878567	Conveyance,Pipe	Other	24in rcp	New	Low	982e6111-3604-4dbb-8a71-14e3cf4b141
353	354	2016-05-23	2016-05-23	1	inspected	40.2382066	-105.2879533	Conveyance,Pipe	Other	4ft cmp	Good	Low	1960ebc9-f88-4471-9271-5e96b082cub9
354	355	2016-05-23	2016-05-23	1	inspected	40.2382544	-105.2881233	Conveyance,Pipe	Other	4ft cmp	Good	Low	42581c07-9593-46f9-bb12-ba1781f5f625
355	356	2016-05-23	2016-05-23	1	inspected	40.2369665	-105.2880233	Conveyance,Pipe	Other	30in cmp	Good	Low	7c871102-7415-4709-a894-ef5d95e96540
356	357	2016-05-23	2016-05-23	1	inspected	40.2366631	-105.2879768	Conveyance,Pipe	Other	30in cmp	Good	Low	77d1ab28-2b11-4017-a106-2561482c0587
357	358	2016-05-23	2016-05-23	1	inspected	40.2310422	-105.2839891	Conveyance,Pipe	Other	30in cmp	Good	Low	15265f18-9aa3-45c5-8771-925525d12200
358	359	2016-05-23	2016-05-23	1	inspected	40.2303779	-105.2836876	Conveyance,Pipe	Other	30in cmp	Good	Low	64b60210-63da-4578-b4fe-f6a671b37ef
359	360	2016-05-23	2016-05-23	1	inspected	40.2305541	-105.2771603	Conveyance,Pipe	Other	3x5ft	Good	Low	4d95c596-42c8-4dbd-89e4-d4226911610
360	361	2016-05-23	2016-05-23	1	inspected	40.2305035	-105.2770637	Conveyance,Pipe	Other	3x5 cmp	Good	Moderate	19679c81-f505-4f6c-900c-f9bc4a922366
361	362	2016-05-23	2016-05-23	1	inspected	40.226608	-105.2735483	Conveyance,Pipe	Other	18in cmp	Good	Low	5a13b4e1-00eb-43a3-bc39-ef9c33c4d70eb
362	363	2016-05-23	2016-05-23	1	inspected	40.2268434	-105.2737779	Conveyance,Pipe	Other	24in cmp	Good	Low	576f5dca-f759-4daf-a902-5d48661bdf82
363	364	2016-05-23	2016-05-23	1	inspected	40.2140224	-105.2742984	Conveyance,Pipe	Other	4ft cmp	Good	Low	ec1d620f-a2ae-44c6-959e-d23cab5c5161
364	365	2016-05-23	2016-05-23	1	inspected	40.2140354	-105.2741814	Conveyance,Pipe	Other	4ft cmp	Good	Low	200eb6c6-0969-4662-a2e2-7a4134d25a3e
365	366	2016-05-23	2016-05-23	1	inspected	40.2141585	-105.2722468	Conveyance,Pipe	Other	18in cmp	Good	Moderate	4a44ef1a-c8f9-4efc-bc45-e8e5d6a2529
366	367	2016-05-23	2016-05-23	1	inspected	40.2142329	-105.2722558	Conveyance,Pipe	Other	18in steel	Good	Moderate	b63be8fd-8d5f-473d-89f5-f68ed40357c
367	368	2016-05-23	2016-05-23	1	inspected	40.2144938	-105.2722378	Conveyance,Pipe	Other	18in steel	Good	Moderate	fa6ba9c-9d2e-4f70-b6f6-54617330fb7
368	369	2016-05-23	2016-05-23	1	inspected	40.2146031	-105.2722344	Conveyance,Pipe	Other	18in steel	Deficient	High	abf4d208-5da9-4150-acde-47100c0b5dbb
369	370	2016-05-23	2016-05-23	1	inspected	40.2141411	-105.2722472	Conveyance,Pipe	Other	18in steel	Good	Low	ca119b4-60a6-4775-817d-4cab25862d0
370	371	2016-05-23	2016-05-23	1	inspected	40.214096	-105.2722467	Conveyance,Pipe	Other	18in steel	Good	Moderate	07ecddba-a69d-424b-8aac-1a10ecc22e100
371	372	2016-05-23	2016-05-23	1	inspected	40.2138975	-105.2722209	Conveyance,Pipe	Other	12in cmp	Good	Low	c21b42a2-0e82-4b8d-a4c9-155c96bf1d7
372	373	2016-05-23	2016-05-23	1	inspected	40.2138155	-105.2722151	Conveyance,Pipe	Other	12in cmp	Good	Moderate	d79c462f-d7e9-423b-a178-39a4ada776b
373	374	2016-05-23	2016-05-23	1	inspected	40.2146142	-105.2721804	Conveyance,Pipe	Other	32in cmp	Good	Low	
374	375	2016-05-23	2016-05-23	1	inspected	40.2146701	-105.272228	Conveyance,Pipe	Other	32in cmp	Acceptable	High	
375	376	2016-05-23	2016-05-23	1	inspected	40.2154468	-105.272265	Conveyance,Pipe	Other	18in cmp	Good	Moderate	1bf8d29e-5f81-4219-8407-b4bd460e7f53
376	377	2016-05-23	2016-05-23	1	inspected	40.2153776	-105.2723723	Conveyance,Pipe	Other	18in cmp	Good	Moderate	d2300ebc-8d87-4450-b674-b09995c65756
377	378	2016-05-23	2016-05-23	1	inspected	40.2168128	-105.2723761	Conveyance,Pipe	Other	18in	Good	Low	r6883ee1-2723-4e07-a080-74ae143dd72c
378	379	2016-05-23	2016-05-23	1	inspected	40.2168672	-105.2723492	Conveyance,Pipe	Other	18in cmp	Good	Low	8631cc57-8b18-4f9f-92ec-2d54e426fa37
379	380	2016-05-23	2016-05-23	1	inspected	40.2173953	-105.2723466	Conveyance,Pipe	Other	18in cmp	Acceptable	Moderate	999e6674-99b6-dcd1-918f-bb0c08ea4397
380	381	2016-05-23	2016-05-23	1	inspected	40.2171543	-105.2723649	Conveyance,Pipe	Other	18in cmp	Good	Moderate	18110a7f-474-40fe-a7ed-c4bc510e278
381	382	2016-05-23	2016-05-23	1	inspected	40.217553	-105.2723969	Conveyance,Pipe	Other	18in cmp	Acceptable	Moderate	39f0f1bc-04d3-48f1-91d4-ae4941fa345
382	383	2016-05-23	2016-05-23	1	inspected	40.217582	-105.2723757	Conveyance,Pipe	Other	18in cmp	Good	Moderate	e75234e-3d3f-48a8-a5d0-b7d6d263902
383	384	2016-05-23	2016-05-23	1	inspected	40.2180502	-105.2725042	Conveyance,Pipe	Other	12in cmp	Acceptable	Moderate	5692f04e-9894-4cc0-9122-481370346f03
384	385	2016-05-23	2016-05-23	1	inspected	40.2180906	-105.2724405	Conveyance,Pipe	Other	12in cmp	Acceptable	Moderate	5e91e424-dbf1-47dc-ad11-fd0af5e26d29
385	386	2016-05-23	2016-05-23	1	inspected	40.2177824	-105.2724537	Conveyance,Pipe	Other	18in cmp	Good	Moderate	a6108382-741b-48cd-9509-597e5fdeb4cb
386	387	2016-05-23	2016-05-23	1	inspected	40.2177186	-105.2724397	Conveyance,Pipe	Other	18in, Mp	Good	Low	2c6f7d9b1-4dbc-420a-91c4-b0499346df3
387	388	2016-05-23	2016-05-23	1	inspected	40.2173164	-105.2724312	Conveyance,Pipe	Other	18in cmp	Good	Low	4bc3ad59-4914-4175-ae30-95cc861074ad
388	389	2016-05-23	2016-05-23	1	inspected	40.2172639	-105.272437	Conveyance,Pipe	Other	18in cmp	Good	Low	7441253d-2736-44c2-9192-bc77b7f5654b
389	390	2016-05-23	2016-05-23	1	inspected	40.2186577	-105.2728708	Conveyance,Pipe	Other	24in cmp	Acceptable	High	4d51f66d-2fd4-4c7e-8d97-972d7dc1ee44
390	391	2016-05-23	2016-05-23	1	inspected	40.2186112	-105.2728991	Conveyance,Pipe	Other	24in cmp	Acceptable	High	1c7b257b-37c2-4dd6-b32e-378d244e513d
391	392	2016-05-23	2016-05-23	1	inspected	40.2203804	-105.271759	Inlet,Grate	Metal	24in	Good	Low	4d736dd9-aab6-460b-b700-19b8ec11f549
392	393	2016-05-23	2016-05-23	1	inspected	40.2203615	-105.2714187	Inlet,Pipe	Other	20in cmp	Good	Low	133e5c4f-226c-4e90-8b6c-8743eb4949ac
393	394	2016-05-23	2016-05-23	1	inspected	40.2203638	-105.2715217	Outlet,Pipe	Other	36in cmp	Deficient	High	7a826b40-ead0-4d80-a97b-238e086aff0a
394	395	2016-05-23	2016-05-23	1	inspected	40.2191018	-105.2610298	Conveyance,Box	Other	10x4ft	Good	High	af62d642-5350-4e6d-bd4a-fd3ebd8a718b
395	396	2016-05-23	2016-05-23	1	inspected	40.2191692	-105.2607349	Conveyance,Box	Other	10x4ft	Good	Moderate	a339059f-ca71-49f5-a7ad-f365f8f69573a
396	397	2016-05-23	2016-05-23	1	inspected	40.220581	-105.2634633	Conveyance,Other	Bridge	10x4ft	Good	Moderate	42100d68-9e67-4c8d-9500-eb5a12d3c69d
397	398	2016-05-23	2016-05-23	1	inspected	40.2190532	-105.2612196	Conveyance,Other	Bridge				102658c2-772a-4d9e-a36a-3f2d85f26ac5
398	399	2016-05-23	2016-05-23	1	inspected	40.2190325	-105.2612955	Conveyance,Other	Irrigation gate				9f7dcca3-3b69-4d0a-b03a-cb789b0fd0f5
399	400	2016-05-23	2016-05-23	1	inspected	40.2134527	-105.2611379	Conveyance,Other	MH				
400	401	2016-05-23	2016-05-23	1	inspected	40.2132806	-105.2615074	Conveyance,Other	MH				
401	402	2016-05-23	2016-05-23	1	inspected	40.2132359	-105.2614555	Inlet,Vault	Other	10ft	New	Low	
402	403	2016-05-23	2016-05-23	2	inspected	40.2261004	-105.2709949	Conveyance,Channel	Concrete		Good	Low	
403	404	2016-05-23	2016-05-23	1	inspected	40.2231931	-105.2651355	Conveyance,Pipe	Other	15in cmp	Good	Low	d6ab7c63-6643-4874-875f-1eb9b332a77d
404	405	2016-05-23	2016-05-23	1	inspected	40.2240491	-105.2653316	Conveyance,Pipe	Other	12in cmp	Good	Low	38003b51-5116-4d36-9f8b-1fbf1b091aa
405	406	2016-05-23	2016-05-23	1	inspected	40.2239219	-105.2653189	Conveyance,Pipe	Other	12in cmp	Acceptable	High	8af0e439-3ebc-4d36-a38b-45926f8b578a
406	407	2016-05-23	2016-05-23	1	inspected	40.2242272	-105.2652983	Conveyance,Pipe	Other	30in pvc	Good	Low	c30ad926-7575-4ce8-ac01-4aaeb50ba30a
407	408	2016-05-23	2016-05-23	1	inspected								

500	0	#####	1	inspected	40.2199739	-105.2552928	Conveyance,Pipe	Other	12in cmp	963e55d7-433e-47f6-89a9-93b436ffba77
501	0	#####	1	inspected	40.2199465	-105.2553807	Conveyance,Pipe	Other	12in cmp	aab7a637-579a-4630-a41b-82f13918f112
502	0	#####	1	inspected	40.2199034	-105.2554534	Conveyance,Pipe	Other	12in cmp	f48d60d0-6f37-40ea-a7cd-7c787a149143
503	0	#####	1	inspected	40.2198845	-105.2555681	Conveyance,Pipe	Other	12in cmp	f7faa7bf-9a0b-4062-94a3-57cfc00f402c
504	0	#####	1	inspected	40.2198821	-105.2555855	Conveyance,Pipe	Other	12in cmp	698a72cc-3669-4b72-8b5c-1de299f1111a
505	0	#####	1	inspected	40.2198559	-105.2556997	Conveyance,Pipe	Other	12in cmp	b7c006ac-125c-4754-88ab-7ea28dcd53ef
506	0	#####	1	inspected	40.2198393	-105.2557593	Inlet,Grate			14f3b1a7-88e9-4cfd-ab87-d143853d7846
507	0	#####	1	inspected	40.2235814	-105.2695394	Inlet,Grate			1e9e5513-c8a0-49b5-b40e-d0ed6a16e4cb
508	0	#####	1	inspected	40.2231087	-105.2704925	Inlet,Grate			d0f81c09-1018-4282-b965-295c29c2b876
509	0	#####	1	inspected	40.2235627	-105.2723591	Inlet,Grate			9d0d229b-fc45-4799-9c27-731e41d5b3cf
510	0	#####	1	inspected	40.2235808	-105.2716376	Inlet,Grate			31c069a7-6932-466e-a7d2-811258b1db94
511	0	#####	1	inspected	40.2235211	-105.2717879	Inlet,Grate			1914f637-ac67-4584-a63c-05352b44df2c
512	0	#####	1	inspected	40.2207155	-105.2555133	Inlet,Pipe	Other	18in rcp	31e40c2b-8bed-46b7-b626-6fc4959481b3
513	0	#####	1	inspected	40.2222825	-105.2546284	Inlet,Pipe	Other	18in rcp	0001a48d-0dd0-463d-a083-fb8529ec974a
514	0	#####	1	inspected	40.2204758	-105.2546525	Inlet,Pipe	Other	18in cmp	cea5e011-7c17-4a93-ba14-a63f09a21110
515	0	#####	1	inspected	40.2208783	-105.2558207	Outlet,Pipe	Other	18in rcp	54bc6d10-879b-4c0d-8f02-2cd845ba8d82
516	0	#####	1	inspected	40.223794	-105.2689607	Outlet,Pipe	Other	18in plastic	90d46665-0491-456a-a88c-e2a8345ce2c0
517	0	#####	1	inspected	40.2246044	-105.2713787	Conveyance,Other	Mh		
518	0	#####	1	inspected	40.2251634	-105.2705453	Inlet,Grate			24ae27c1-62f5-4755-bb38-f642c1685983
519	0	#####	1	inspected	40.2243216	-105.2669231	Inlet,Pipe	Other	48x60 r p	23d58aac-88f1-46e3-9f26-b6b5d4668c36
520	0	#####	1	inspected	40.2245235	-105.2672286	Outlet,Pipe	Other	24in rcp	3a50a612-da18-4eab-8dbe-3fb2e7e8ff1